



## Customer Service Report

Customer: Bradley Pond  
 Customer ID: \_\_\_\_\_  
 Field Biologist: Paul Mosteller

Date of Visit: 9/6/2023  
 Weather: 0 °F High  
95% ☁

### Waterway and Ditch Treatments

Site	1	2	3	4											
Algae		x	x												
Submersed Weeds															
Shoreline Grasses & Brush															
Floating Weeds															
Mosquito Larvicide															
Pond Dye															
Inspection	x														
Debris Removal		x	x	x											

Comments: Ponds 2 and 3 were treated for algae and trash was removed from the algae mats and off the banks. Pond 4's trash was removed. Pond 1 received an inspection. Please note: due to the cancellation of schools from the hurricane, this visit served as the August visit, we will return before the end of September.

Carp Program  
 Carp Observed  
 Barriers Inspected

Flow  
 None  
 Slight  
 Visible

Water Clarity  
 < 1'    2-4'  
 1-2'    >4'

Water Levels  
 High  
 Normal  
 Low

### Fish/Wildlife Observations

- |                                   |   |                                    |   |   |
|-----------------------------------|---|------------------------------------|---|---|
| <input type="checkbox"/> Bass     | <input type="checkbox"/> Anhinga              | <input type="checkbox"/> Woodstork | <input checked="" type="checkbox"/> Turtles | <input type="checkbox"/> Other Species: _____ |
| <input type="checkbox"/> Bream    | <input checked="" type="checkbox"/> Cormorant | <input type="checkbox"/> Ducks     | <input type="checkbox"/> Snakes             | _____   |
| <input type="checkbox"/> Catfish  | <input type="checkbox"/> Egrets               | <input type="checkbox"/> Osprey    | <input type="checkbox"/> Alligator          | _____   |
| <input type="checkbox"/> Gambusia | <input type="checkbox"/> Herons               | <input type="checkbox"/> Ibis      | <input type="checkbox"/> Frogs              | _____   |

### Native/Beneficial Vegetation Noted

- |                                       |                                       |                                   |  |
|---------------------------------------|---------------------------------------|-----------------------------------|--|
| <input type="checkbox"/> Arrowhead    | <input type="checkbox"/> Bulrush      | <input type="checkbox"/> Lotus    | <input type="checkbox"/> Slender Spikerush   |
| <input type="checkbox"/> Cordgrass    | <input type="checkbox"/> Lily         | <input type="checkbox"/> Chara    | <input type="checkbox"/> Blue Flag Iris      |
| <input type="checkbox"/> Bacopa       | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> Naiad    | <input type="checkbox"/> Bladderwort         |
| <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Spatterdock  | <input type="checkbox"/> Eelgrass | <input checked="" type="checkbox"/> Pondweed |

Did you know? Otoliths, commonly known as "ear stones," are hard, bone-like structures located directly behind the brain of bony fishes. These structures aid fish in balance and hearing.



## Customer Service Report

Customer: Bradley Pond  
Customer ID: \_\_\_\_\_  
Field Biologist: Paul Mosteller

Date of Visit: 9/6/2023  
Weather: 0 °F High  
95% ☁️



Pond 03



Pond 02



Pond 01



Pond 04

Did you know? Otoliths, commonly known as "ear stones," are hard, bone-like structures located directly behind the brain of bony fishes. These structures aid fish in balance and hearing.