



CUSTOMER SERVICE REPORT

Customer: Bradley Pond
 Customer ID: J19287
 Field Biologist: Haylee

Date of Visit: 9/15/2023
 Weather: 82 °F High
 80% ☁

WATERWAY AND DITCH TREATMENTS

Site	1	2	3	4											
Algae															
Submersed Weeds															
Shoreline Grasses & Brush	X	X	X	X											
Floating Weeds															
Mosquito Larvicide															
Pond Dye	X														
Inspection															
Debris Removal															

COMMENTS: I sprayed shoreline grasses on ponds 1, 2, 3, and 4 and added pond dye to pond 1.

CARP PROGRAM

- Carp Observed
- Barriers Inspected

FLOW

- None
- Slight
- Visible

WATER CLARITY

- < 1'
- 1-2'
- 2-4'
- >4'

WATER LEVELS

- High
- Normal
- Low

FISH/WILDLIFE OBSERVATIONS

- | | | | | |
|-----------------------------------|------------------------------------|---|------------------------------------|--|
| <input type="checkbox"/> Bass | <input type="checkbox"/> Anhinga | <input type="checkbox"/> Woodstork | <input type="checkbox"/> Turtles | <input type="checkbox"/> Other Species:
<hr/> <hr/> <hr/> |
| <input type="checkbox"/> Bream | <input type="checkbox"/> Cormorant | <input checked="" type="checkbox"/> Ducks | <input type="checkbox"/> Snakes | |
| <input type="checkbox"/> Catfish | <input type="checkbox"/> Egrets | <input type="checkbox"/> Osprey | <input type="checkbox"/> Alligator | |
| <input type="checkbox"/> Gambusia | <input type="checkbox"/> Herons | <input type="checkbox"/> Ibis | <input type="checkbox"/> Frogs | |

NATIVE/BENEFICIAL VEGETATION NOTED

- | | | | |
|--|---------------------------------------|-----------------------------------|---|
| <input type="checkbox"/> Arrowhead | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Lotus | <input checked="" type="checkbox"/> Slender Spikerush |
| <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Lily | <input type="checkbox"/> Chara | <input type="checkbox"/> Blue Flag Iris |
| <input checked="" type="checkbox"/> Bacopa | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> Naiad | <input checked="" type="checkbox"/> Bladderwort |
| <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Spadderdock | <input type="checkbox"/> Eelgrass | <input type="checkbox"/> Pondweed |

DID YOU KNOW? Otoliths, commonly known as "ear stones," are hard, bone-like structures located directly behind the brain of bony fishes. These structures aid fish in balance and hearing.



CUSTOMER SERVICE REPORT

Customer: Bradley Pond
Customer ID: J19287
Field Biologist: Haylee

Date of Visit: 9/15/2023
Weather: 82 °F High
80% ☁



Pond 1



Pond 2



Pond 3



Pond 4

DID YOU KNOW? Otoliths, commonly known as "ear stones," are hard, bone-like structures located directly behind the brain of bony fishes. These structures aid fish in balance and hearing.